



Existing areas of natural vegetation

Surface water sewer below ground

Mown grass

4 no Orchard trees

PLAY AREA

Existing semi-natural vegetation

Indicative planting positions - final location to be determined on site

2 no Crack willow

Existing and new planting buffered by areas of reduced mowing to encourage wildflowers and pollinating insects

PLAYING FIELD

FLOODPLAIN PLANTING MIX-1

2 no Native Black Poplar - male

Assumed locations of land drains for football pitch

Underground electricity cable - to be checked on site by Western Power Distribution

- 15 no Alder buckthorn
- 61 no Common Alder
- 30 no Hazel
- 76 no Grey willow
- 9 no Oak
- 8 no White willow
- 8 no Crack willow
- 8 no White Poplar
- 15 no Aspen
- 2 no Native Black Poplar - male
- 61 no Downy birch

BANK PLANTING MIX-1

1 no Native Black Poplar - male

- 7 no Rowan
- 3 no Blackthorn
- 7 no Elder
- 7 no Hawthorn
- 3 no Crab Apple
- 14 no Goat Willow
- 14 no Hazel
- 4 no Oak
- 3 no Wild cherry
- 3 no Field rose

Trees for Congleton Site
St John's Recreation Ground

Title **Planting plan - north** Date **06/11/21**

Drawing Number **21-22/SJ/2**

Drawn By **RB**

Scale **1:750@A3**

NOTE: Trees and shrubs to be planted at average 1.5 m spacing
 Where planting location is within areas of natural vegetation growth, tree shelters are to be used.

