



1 no Crack willow

2 no Native Black Poplar - female

SMALL FOOTBALL PITCH AREA

BANK PLANTING MIX-2

- 4 no Rowan
- 2 no Blackthorn
- 4 no Elder
- 4 no Hawthorn
- 2 no Crab Apple
- 8 no Goat Willow
- 8 no Hazel
- 2 no Oak
- 2 no Wild cherry
- 2 no Field rose

Indicative planting positions - final location to be determined on site

Existing semi-natural vegetation on embankment

FLOODPLAIN PLANTING MIX-2

- 7 no Alder buckthorn
- 28 no Common Alder
- 14 no Hazel
- 35 no Grey willow
- 4 no Oak
- 3 no White willow
- 3 no Crack willow
- 3 no Aspen
- 1 no Native Black Poplar - female
- 28 no Downy birch

1 no Crack willow

Existing areas of natural vegetation

Underground electricity cable - to be checked on site by Western Power Distribution

Mown grass

Existing and new planting buffered by areas of reduced mowing to encourage wildflowers and pollinating insects

FLOODPLAIN PLANTING MIX-3

- 7 no Alder buckthorn
- 27 no Common Alder
- 14 no Hazel
- 34 no Grey willow
- 4 no Oak
- 3 no White willow
- 3 no Crack willow
- 3 no Aspen
- 1 no Native Black Poplar - male
- 27 no Downy birch

NOTE:

Trees and shrubs to be planted at average 1.5 m spacing
Where planting location is within areas of natural vegetation growth, tree shelters are to be used.

Trees for Congleton Site		
St John's Recreation Ground		
Title	Planting plan - south	Date
		06/11/21
Drawing Number	21-22/SJ/3	Scale
		1:750@A3
Drawn By	RB	